

**Simulations**  
**Photos**  
**All Graphics (no plans)**









Window 7




Window 10




Left: window hinge hardware. Center: window operator crank. Right: window lock handle.






Site. North is at top






Window 1 in carport facing west




Window 2 in carport facing west






Site: Street view north side of house: 6713 E Granada Rd. 85257




Site: Back view south side of house







Window 3 facing north



Window 4 facing north




Window 5 facing east




Window 6 facing east







Window 7 facing South



Window 7 cracks in panes facing South




Window 8 facing south




1. Window 9 facing South







Window 10 cracked caulking facing South



Window 10 facing South




Door 1 in carport facing north



Door 2 facing west






Patio door 3 facing east



Front door 4A facing west



Front Screen door 4B facing west