

STRUCTURAL INSPECTION

#300112

S.E. CONSULTANTS, Inc.
Structural Engineering Consultants


5800 East Thomas Road, Suite 104 Phone: (602) 946-2010
Scottsdale, AZ 85251 Fax: (602) 946-1909

TO BRAXTON BUILDERS

FROM S.E. CONSULTANTS

REPORT NO. <u>#2</u>	ARRIVAL <u>11:30</u> DEPARTURE <u>12:00</u>
DATE <u>11/8/24</u>	JOB NO. <u>2005-22</u>
PROJECT <u>CORK RESIDENCE</u>	
LOCATION <u>SCOTTSDALE, AZ</u>	
CONTRACTOR <u>BRAXTON</u>	
WEATHER <u>CLEAN</u>	TEMP <u>58</u> °at AM PM
PRESENT AT SITE <u>CORK</u>	

ITEMS INSPECTED EPOXY (HOLD DOWN)



OBSERVATIONS AS PER PLANS SIMPSON
EPOXY BLOWN OUT BRUSH OUT

SUPERINTENDENT _____

SIGNED [Signature]
Inspector