

**Simulations**  
**Photos**  
**All Graphics (no plans)**



















953-PA-2015



2221 North 72nd Place, Scottsdale AZ 85257

15-HP-2015  
12/0215



Picture from 72nd Place & Monte Vista. Deteriorated Swamp cooler and old antennas will be removed as part of the project.

953-PA -2015



15-HP-2015  
12/0215

Open pergola and entry way, visible from 72nd Place. Picture shows deteriorated wood.

953-PA-2015



Open Entry way.

15-HP-2015  
12/0215

953-PA-2015



Picture of deteriorated: wood, trim, tongue and groove, fascia and pergola.

953-PA-2015



Damage: fascia, open framing (walkway)

15-HP-2015  
12/0215

953-PA-2015



Town & Country Haver Home with flat white roof.

15-HP-2015  
12/0215

953-PA - 2015



Front view of property, from 72nd Place

**15-HP-2015**  
**12/0215**

953-PA-2015



View of property from street.  
(72nd Place)

**15-HP-2015**  
**12/0215**

953-PA-2015



Open Entry way.

15-HP-2015  
12/0215

953-PA-2015



Deterioration of fascia board. Back of property.


15-HP-2015  
12/0215

953-PA-2015



Side view of property, from Monte Vista. Project will remove deteriorated Swamp Cooler.

953-PA-2015



Town & Country Haver Home showing proper drip edge.

15-HP-2015  
12/0215

953-PA-2015



Damage: tongue + groove, fascia board

15-HP-2015  
12/0215



15-HP-2015  
12/0215

(Green-Alpen) Equipment

953-PA-2015



Damage: tongue & groove, fascia board

15-HP-2015  
12/0215

953-PA-2015



15-HP-2015  
12/0215

Open framing (walk way), wood framing over entry

953-PA-2015



15-HP-2015  
12/0215

wood framing above walk way (Remove, restore to original.)

953-PA-2015



15-HP-2015  
12/0215

Wood framing over front patio (remove)

953-PA-2015



15-HP-2015  
12/0215

Damage: Wood framing, car port beam

953-PA-2015



15-HP-2015  
12/0215

Damage: fascia

953-PA-2015



Damage: fascia, tongue & groove

15-HP-2015  
12/0215


953-PA-2015



15-HP-2015  
12/0215

Damage: fascia

953-PA-2015



15-HP-2015  
12/0215

Damage: fascia under metal fascia wrap

953-PA-2015



15-HP-2015  
12/0215

Damage: fascia, tongue & groove

953-PA-2015



Damage

15-HP-2015  
12/0215

953-PA-2015



15-HP-2015  
12/0215

Pamseye

953-PA-2015



15-HP-2015  
12/0215

Damage

953-PA-2015



15-HP-2015  
12/0215

Damage

953-PA-2015



15-HP-2015  
12/0215

Damage

953-PA-205



15-HP-2015  
12/0215

Damage

953-PA-2015



15-HP-2015  
12/0215

Damage

953-PA-2015



Damage

953-PA-2015



15-HP-2015  
12/0215

Damage

953-PA-2015



15-HP-2015  
12/0215

Damage

953-PA-2015



15-HP-2015  
12/0215

Remove old antennas + dish satellite


155 TR 2015



15-HP-2015  
12/0215

Town + Country Haver Home with good facia

953-PA-2015



Town + Country Haver Home with good floor

15-HP-2015  
12/0215