

# 280115


# Hart Engineering LLC

structural consultant

PROJECT Kimbrough Res.

LOCATION 12606 N. 128<sup>th</sup> Pl.  
Scottsdale, AZ

CLIENT Collective Construction



PURPOSE Structural Inspection for conformance to the City-approved plans and the Building Code.

INSPECTION #	DATE	TIME
<u>4</u>	<u>6/29/23</u>	<u>5:00 pm</u>

## REMARKS

Inspected ICF construction.

- Inspection is based on pictures and videos provided. These showed some of the reinforcing and grouting/casting of concrete.

- Matt Lamb stated that the City did inspections of the reinforcing, so I am relying on those inspections for verification that reinforcing was correct for the ICF walls.

→ Inspection approved.

# 280115


# Hart Engineering LLC

structural consultant

PROJECT Kimborough Res.

LOCATION 12606 N. 128<sup>th</sup> Pl  
Scottsdale, AZ

CLIENT Collective Construction



PURPOSE Structural Inspection for conformance to the City-approved plans and the Building Code.

INSPECTION #	DATE	TIME
<u>3</u>	<u>6/20/23</u>	<u>12:15 pm</u>

REMARKS

• Inspected structural steel and field welding.

→ Inspection approved.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_