

STRUCTURAL INSPECTION

300112
MAY 13
09/05/2024

S.E. CONSULTANTS, Inc.

Structural Engineering Consultants

5800 East Thomas Road, Suite 104 Phone: (602) 948-2010
Scottsdale, AZ 85251 Fax: (602) 948-1809

TO CHARLES CORK

FROM S.E. CONSULTANTS

ITEMS INSPECTED RETAINING WALL AZ


OBSERVATIONS AS PER PLANS. READY TO
PROCEED.

SUPERINTENDENT

SIGNED

Inspector

REPORT NO	#5	ARRIVAL	10:00
		DEPARTURE	11:00
DATE	5/16/24	JOB NO.	2005-22
PROJECT	CORK RESIDENCE		
LOCATION	10789 E. TROON N.		
CONTRACTOR	BRAXTON BUILDERS		
WEATHER	CLEAR	TEMP	° at AM PM
PRESENT AT SITE	CHARLES CORK		



STRUCTURAL INSPECTION

S.E. CONSULTANTS, Inc.

Structural Engineering Consultants

5800 East Thomas Road, Suite 104
Scottsdale, AZ 85251

Phone: (602) 946-2010
Fax: (602) 946-1909

REPORT NO. # 4

ARRIVAL 10:11
DEPARTURE 11:00

DATE 5/2/24

JOB NO. 2005-22

PROJECT CORK RESIDENCE

LOCATION 10789 E TROON NORTH

CONTRACTOR BRAXTON BUILDERS

WEATHER CLEAR


TEMP 70's at 10 AM
PM

PRESENT AT SITE CHARLES CORK

TO CHARLES CORK

FROM S.E. CONSULTANTS

ITEMS INSPECTED FASTENING FOR RETAINING WALLS



OBSERVATIONS AS PER PLANS MAY POUR
CONCRETE

SUPERINTENDENT

SIGNED

Inspector

STRUCTURAL INSPECTION

S.E. CONSULTANTS, Inc.

Structural Engineering Consultants

5800 East Thomas Road, Suite 104
Scottsdale, AZ 85251

Phone: (602) 946-2010
Fax: (602) 946-1909

TO BRAXTON BUILDERS

FROM S.E. CONSULTANTS

ITEMS INSPECTED GRANT


OBSERVATIONS AS PER PLAN. 2ND FLT.

SUPERINTENDENT _____

SIGNED _____

Inspector

REPORT NO. <u>3</u>	ARRIVAL <u>8:16</u> DEPARTURE <u>8:45</u>
DATE <u>3/18/24</u>	JOB NO. <u>2005-22</u>
PROJECT <u>CORK RESIDENCE</u>	
LOCATION <u>SCOTTSDALE AZ</u>	
CONTRACTOR <u>BRAXTON BUILDER</u>	
WEATHER <u>CLEAR</u>	TEMP <u>OFF</u> ° at <u>AM</u> PM
PRESENT AT SITE <u>CHARLE CORK</u>	



STRUCTURAL INSPECTION

S.E. CONSULTANTS, Inc.
Structural Engineering Consultants


5800 East Thomas Road, Suite 104 Phone: (602) 946-2010
Scottsdale, AZ 85251 Fax: (602) 946-1909

TO BRAXTON BUILDER

FROM S.E. CONSULTANT

REPORT NO. <u>2</u>	ARRIVAL <u>7:30</u> DEPARTURE <u>9:30</u>
DATE <u>3/13/24</u>	JOB NO. <u>2005-12</u>
PROJECT <u>CORK RESIDENCE</u>	
LOCATION <u>SCOTTSDALE AZ</u>	
CONTRACTOR <u>BRAXTON BUILDER</u>	
WEATHER <u>CLEAR</u>	TEMP ° at <u> </u> AM PM
PRESENT AT SITE <u>CHARLE CORK</u>	

ITEMS INSPECTED COASTING RETAINING WALLS



OBSERVATIONS (CREATED) / 4' LIFT. AS PER PLANS

SUPERINTENDENT _____

SIGNED _____

Inspector

STRUCTURAL INSPECTION

S.E. CONSULTANTS, Inc.

Structural Engineering Consultants

5800 East Thomas Road, Suite 104
Scottsdale, AZ 85251

Phone: (602) 946-2010
Fax: (602) 946-1909

TO MR. COLE

FROM S.E. CONSULTANTS

ITEMS INSPECTED FOOTINGS FOR RETAINING WALL

OBSERVATIONS AS PER PLANS.

REPORT NO. #1

ARRIVAL 8:00

DEPARTURE 2:30

DATE 2

JOB NO. 2009-22

PROJECT

COLE RESIDENCE

LOCATION 10709 E. TRACON

CONTRACTOR

BRANTON BUILDERS

WEATHER


CLEAR

TEMP

70° at

AM
PM

PRESENT AT SITE MR. COLE



Expires: 12/31/2026

SUPERINTENDENT

SIGNED

Inspector